INNOVATION TECH™ AIR PRO SERIES USER MANUAL

..... ••••• $\bullet \bullet \bullet$ • $\bullet \bullet \bullet$ •• •••• ••••• •••••

...



••

....

....

...

arkiplot.com

Start Your Business From Here

4054050PSI-N



4054050PSI-NX

4054050PSI-2N

NOTICE

1.Use the heat transfer press only as intended 2.Please keep children away from the machine 3.Make sure correct outlet before use the device 4.Burns can occur from contact with hot surface 5.Please choose a at least 35L air comprossor 6.Turn off the device when not in use and remove the power plug

- In the Box -----
- Product Features ------
- Display setting ------
- Operation Instruction ------
- Transfer Parameters ------
- Troubleshooting -----



_	_	_	_	_		_	_	_		 	 -		-	01/03/05
_	_	_	_	_	_	_	_	_	_	 	 _		-	02/04/06
_	_	_	_	_	_	_	_	_	_	 	 _	_	-	07/08
_	_	_	_	_	_	_	_	_	_	 	 _	-	-	09/10
_	_	_	_	_	_	_	_	_		 	 _		-	11
_	_	_	_	_	_	_	_	_		 	 _		-	12





arkiplot@arkiplot.com


Innovation Tech[™] Air Pro One (Single Platen)

MACHINE INTRODUCTION

ArkiPress 4050PSI-N



In the box



before use the heat press



- Control Display
 Heating Plate Cover
 Alu. Lower Plate
- Silicon Mat
 Drawer Handle
- 6. Swing-arm Han


	7. Operation Buttons	10. Breakers
е	8. Release Button	11. Power Outlet
indle	9. Power Switch	12. Air Regulator

— *02* —

Innovation Tech[™] Air Pro X (Movable Caddie)

MACHINE INTRODUCTION

ArkiPress 4050PSI-NX



In the box







1. Control Display
2. Heating Plate Cover
3. Alu. Lower Plate

4. Silicon Mat

- 5. Height Adjust Knob
- 6. Rotation Adjust Knob




- 7. Brake Caster
- 8. Operation Button
- 9. Quick Release Button
- 10. Swing-arm
- 11. Power Outlet
- 12. Power Switch
- 13. Air Regulator

- 04 -

ArkiPress 4050PSI-2N



In the box














1. Control Display	
2. Heating Plate Cove	r
3. Silicone Mat	

4. Alu. Lower Plate 5. Quick Change System 6. Adjustable Base

MACHINE INTRODUCTION



- 06 -

CONTROLLER PROGRAM

PV: Present Value : Set Value SV heatpress Ľ Celsius Read-out °F : Fahrenheit Read-out **PV** $\Omega \Omega \Omega$ 888 : Timing in Seconds : Temperature Digits Ð Heating Indicator Timing $\mathbf{\tilde{c}}$ Decrease Digits SET COUNTER 8888 Plus Digits (Long hold for temperature calibration) IT9300 **Counter Clearance** (X) (L) Set Mode (Long Hold)





Control Panel Display



P-3 : °C or °F Read-out Touch SET & ↑↓ buttons to set °C or °F





Auto-off Introduction It reads OFF and machine starts to cool down after machine raises to SET temp. and remains no operation for P-4 set time. Operation like control panel setting or heat pressing.



CONTROL SETTING

Touch SET & $\uparrow \downarrow$ buttons to set desired Temp.

P-3 : °C or °F Read-out Touch SET & $\uparrow \downarrow$ buttons to set °C or °F



Wake Machine from Sleepv Mode You can wake up the heat press from sleepy mode by touching any button on the control panel, and machine starts to heat again.



P-2 : Time Setting Mode Touch SET $\& \uparrow \downarrow$ buttons to set desired time.



P-4 : Auto Power-off Mode Touch SET & $\uparrow \downarrow$ buttons to set auto-off time with 0-120 mins range



Clear Counter NO. You can long hold the CLEAR button to clear the COUNTER NO. on the panel.

USERTIPS

User Operation



Socket & connect to power outlet and power-on the heat press. (Tip: Press the tiny clip when you pull off the socket)



Position the substrate and preheat to remove the wrinkles or moisture, continue to place the graphics design on paper or vinyl on substrate and cover with a Teflon sheet.



Two hands press the operation buttons to let down the heating platen and start the heat pressing.

Take off the T-shirt and peel off the vinyl or paper depends on cold peel or hot peel.

Place the T-shirt with Teflon sheet and go for another 5 sec. heat pressing, then finishes the transfer!





Innovation Tech™ device is able to use additional 5 lower platens, the quick change needs no tool, platen sizes are 13x13cm (tag or label), 18x38cm (trousers), 12x45cm (sleeves), 30x35cm (child garments) and 12x36cm (shoes)



1/4 in. (8mm outer diameter) air hose & MNPT fittings are required. MNPT fittings link between air hose and air compressor, air hose is inserted into air regulator's tube connector. (Tube connector for dual station air machine locates on machine right side which is over the red power witch). Air hose and MNPT fittings do not involved in heat press order, please order them with air compressor, the chosen air compressor should be at least 35L.



Control panel P-4 is auto power-off setting with range 0-120min, 0 refers to not going enter into sleepy mode. As long as machine reaches to the set Temp. and is kept no in use for set time Say. 60mins, machine will enter into sleepy, display shows OFF and temperature cools down. You could touch any button on the control panel to wake up the machine.



You could adjust the air pressure by air regulator, simply pull-up the black cap on its top, clockwise to increase, recommended pressure read-out 0.4-0.7Mpa.



Set recommended TEMP, TIME settings on page 11.




Wait for heat press heats up to the set temperature, the fire icon shows heating now.







After ten thousands of swing-away and press, maybe you need to adjust the position screw o n the back column to make sure the upper heating platen and lower platen is always paralleled. (For Air Pro One and X)



It's ordinary if you feel some drag force when you slide out or slide back the lower platen, as Magnetic Tech is applied, which makes sure lower platen won't slide back when you are threading a T-shirt, also makes sure upper & lower platens are in correct location after you slide the drawer back.(For Air Pro One and X)



There are two knob on the moveable caddie. upper knob is for caddie height adjustment (Max. 10cm), the lower knob is for anti-rotation, you can move around the upper machine when lower knob is in loosen status. (for Air Pro X only)

- 10 -

×._____

Transfer Parameters

Troubleshooting

Transfer Material	Base Material	Printer	Device	Temperature	Time	Pressure	Remarks
	Light color polyester fabric	Micro piezoelectric		200°C	25~35s	Heavy	Mirror your design when printing on sublimation paper
Sublimation paper	Light color cotton fabric	inkjet Epson & Ricoh printers	Innovation Tech Heat Press				
	Non woven fabric bags	with CISS & sublimation ink					
Light color inkjet	Light color polyester fabric			185°C	15~25 s	Medium	
& laser transfer	Light color cotton fabric	Inkjet printer with					
paper	Non woven fabric bags	pigment ink &					
Dark color inkjet	Dark color polyester fabric	inkjet paper. Laser printer with	Innovation Tech™ Heat Press	165°C	15s		Teflon sheet is required
& laser transfer	Dark color cotton fabric	laser paper.					
paper	PUleather						
	Polyester fabric			150~160°C	8~15s		Check beforehand if your HTV requires hot or cold peel
Heat transfer vynil (HTV)	Cotton fabric	Cutting plotters					
	Knit fabrics				10~15s		

Q:When pressed onto the garments, the color of the design is faded, or transfers are not fully stacked onto the garments.

enough time. You may need to try more to get right temp, time and pressure.

Q:The transfers are stacked on the heating platen.

A: Transfers like dark ink-jet transfer paper could be stacked on heating platen, you should use a Teflon sheet to cover the transfer paper. If this happen, please turn-off and cools machine completely before you try to peel the stacked paper, do not use sharp item like knife to scrape the heating platen as Teflon maybe scratched.

Q: Hard to peel off the transfer paper or vinyl.

A: Please make sure transfers are warm peel or cold peel, so as to peel off accordingly.

Q: LCD control panel shows "000".

A: That refers the thermocouple wire is disconnected, you shall turn to support team for help and replace the disconnected connection.

Q: How to get a reasonable pressure.

A: Adjust the pressure know and try to lock down the handle, feel there is certain large resist force.

Q: Turn on the power, but the heat press does not work.

A: Pls check the power plug connected well to the socket, you may turn to support team if problem is still remaining.

A: Reason comes from three points, the pressure is no enough, the temperature is not hot enough or the design has not been pressed for

Any further help, please contact our support team.

- 12 -